

Colonel. Barrett Farm
Room 102 - Entry

	A	B	C	D	E	F
1	sample ID	CBF-102-A	CBF-102-B	CBF-102-C	CBF-102-D	CBF-102-E
2	investigated by	JBV	JBV	JBV	JBV	JBV
3	date	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10
4	elevation	south	south	south	west	west
5						
6	feature	horizontal plank wall	horizontal plank wall	horizontal plank wall	vertical wall board	vertical wall board
7	element	3rd board from bottom	lowest board	lowest board	S most board /door casing	S most board /door casing
8	detail					
9						
10	location	W of front door	above baseboard area	@ mopboard level	above mopboard	@ mopboard level
11			W of front door	W of front door		
12				behind newer baseboard		
13						
14	notes	area had been encapsulated by door surround	area had possibly been encapsulated by?	painted mopboard		suspect red matches baseboard in 103?
15						no orangish mopboard observed
16						
17	substrate	wood	wood	wood	wood	wood
18	finishes	translucent reddish wash	translucent reddish wash	dark wash		translucent reddish wash
19		light blue gray	light blue gray		light blue gray	blue gray
20		translucent? yellowish green			glaze?	glaze?
21						red
22		green	green	yellowish green	green	green
23				glaze		glaze?
24		gray	gray	orangish red, partially translucent	gray	gray
25		off-white (extant)	off white		off white	multiple off whites
26			off white		off white	
27						
28						
29						
30						
31						
32						
33						

Suspected finish campaigns are highlighted as follows: 1st campaign in red, 2nd campaign in blue, 3rd campaign in green
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.

Colonel. Barrett Farm
Room 102 - Entry

	A	G	H	I	J	K
1	sample ID	CBF-102-F	CBF-102-G	CBF-102-H	CBF-102-I	CBF-102-J
2	investigated by	JBV	JBV	JBV	JBV	JBV
3	date	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10
4	elevation	west	west	west	west	west
5						
6	feature	door to 101	door to 101	door to 101	doorway to 101	stair
7	element	lower rail	center stile	lower S panel	beaded door casing	painting apron
8	detail					
9						
10	location	@ mopboard level				near foot of stairs
11						
12						
13						
14	notes	painting mopboard		panel + panel surround same	blue or green gray 2nd layer may be	no red solid color seen on stairs in apron area
15		approx. 3 1/2 " from bottom of door			slight poly or likely degradation	
16						
17	substrate	wood	wood	wood	wood	wood
18	finishes	wash	wash	wash	wash	wash
19		lt. blue gray	blue gray/green	greenish gray	blue gray	blue gray or green (degraded)
20		glaze	glaze		glaze	glaze
21		red (2?)				
22		green	green	yellowish green	yellowish green	yellowish green
23		glaze?				orangish
24		gray - distinct	gray	gray	gray	blue gray (differs from distinct gray)
25		multiple off whites	multiple off whites	multiple off whites	same...	
26						
27						
28						
29						
30						
31						
32						
33						

Suspected finish campaigns are highlighted as follows: 1st campaign in red, 2nd campaign in blue, 3rd campaign in green
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.

Colonel. Barrett Farm
Room 102 - Entry

	A	L	M	N	O	P	Q
1	sample ID	CBF-102-K	CBF-102-L	CBF-102-M	CBF-102-N	CBF-102-O	CBF-102-P
2	investigated by	JBV	JBV	JBV	JBV	JBV	JBV
3	date	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10
4	elevation	north	north	north	n/a	n/a	n/a
5							
6	feature	vertical plank wall	vertical plank wall	vertical plank wall	stairs	stairs	stairs
7	element	E most board	2nd board from E	W most board	base triangle at bottom of stairs	outside stair apron	balustrade base
8	detail		@ mopboard area			above base triangle	
9							
10	location	relocated from another area?	viewed over 4" above wood floor				
11			don't know where mopboard ends				
12							
13							
14	notes	1st drk gray differs from others	secondary painted mopboard		2 campaigns painted mopboard		wash not seen but could be there
15		green differs from others					
16							
17	substrate	wood	wood	wood	wood	wood	wood
18	finishes	wash	wash	wash	translucent reddish wash	translucent reddish wash	
19		dark gray (different)	dark green muddy	very dark gray	red (opaque)	blue gray	gray
20		glaze					
21							
22		green (different)	yellowish green	light greenish	yellowish green	yellowish green	yellow green
23			orangish		orangish red		
24		light gray	dark gray	light gray	dark gray	light gray	gray
25		multiple off whites	multiple off whites	multiple off whites	multiple off whites	multiple off whites	multiple off whites
26							
27							
28							
29							
30							
31							
32							
33							

Suspected finish campaigns are highlighted as follows: 1st campaign in red, 2nd campaign in blue, 3rd campaign in green
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.

Colonel. Barrett Farm
Room 102 - Entry

	A	R	S	T	U	V	W	X
1	sample ID	CBF-102-Q	CBF-102-R	CBF-102-S	CBF-102-T	CBF-102-U	CBF-102-V	CBF-102-W
2	investigated by	JBV	JBV	JBV	JBV	JBV	JBV	JBV
3	date	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10
4	elevation	n/a	n/a	n/a	north	n/a	S/E	east
5								
6	feature	stairs	stairs	stairs	plaster wall	stairs	SE post casing	doorway to 103
7	element	baluster	newel post	handrail	stair apron area	riser		S door casing
8	detail		bottom of stairs	bottom of stairs		edge near plaster wall		above mopboard area
9								
10	location					on landing		
11								
12								
13								
14	notes	same as balusters upstairs	same as upstairs	1st gray different but all other layers appear same as 102-R	secondary painted mopboard	seems to be missing 1st blue gray		
15					should sample- has finishes	see 202-F, may be unfinished at initial campaigns		
16								
17	substrate	wood	wood	wood	plaster	wood	wood	wood
18	finishes						translucent wash	translucent
19		gray	darker gray	dark gray green (different than 101-R)			gray blue	gray blue
20		glaze?	glaze	glaze				
21						translucent		
22		green	green	green	yellow green	green	green	yellowish green
23					orangish red			
24		gray	greenish gray	greenish gray		gray	light gray	light gray
25		multiple off whites	dark brown? poss. translucent?	dark brown? poss. translucent?		multiple off whites	multiple off whites	multiple off whites
26			multiple reds (5 at least)	multiple reds (5 at least)		later layers		
27			yellow	yellow				
28			gray	gray				
29			blue	blue				
30								
31								
32								
33								

*Suspected finish campaigns are highlighted as follows: 1st campaign in red, 2nd campaign in blue, 3rd campaign in green
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.*