

Colonel Barrett Farm
Room 104 - Kitchen

	A	B	C	D	E	F
1	sample ID	CBF-104-A	CBF-104-B	CBF-104-C	CBF-104-D	CBF-104-E
2	investgated by	JBV	JBV	JBV	JBV	JBV
3	date	1/13/10	1/13/10	1/13/10	1/13/10	1/13/10
4	elevation	south	south	north	north	n/a
5						
6	feature	door to 103	door to 103	horizontal plank wall	horizontal plank wall	stair
7	element	jamb & casing	E stile	3rd board from bottom	at white painted area	tread - @ edge
8	detail					labeled "2nd & 3rd tread & riser"
9						removed element in kitchen
10	location	east jamb & casing			at foot of stairs	
11						
12	notes	jamb does not initially match door	not an early door		not many finishes	green splatter noticed- not seen w/scope
13		beaded casing looks same	lower E panel & rail look same		white modern	riser same
14						infil piece- no early wash
15						
16						
17	substrate	wood	wood	wood	wood	wood
18	finishes	iron oxide? wash	yellowish/greenish	iron oxide? wash	iron oxide? wash	iron oxide? wash
19		yellow	off-white greenish		white (modern)	white
20		glaze	off-white greenish			
21		yellow	greenish brown			
22		yellow/gold (visible)	yellow/gold			
23		yellow/gold	(later, flaking whitish layers)			
24		bright green				
25		bright green				
26		blue				
27		light green				
28		light yellow				
29		light yellow				
30		blue				
31		blue				
32						
33						

*Suspected finish campaigns are highlighted as follows: 1st campaign in red.
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.*

Colonel Barrett Farm
Room 104 - Kitchen

	A	G	H	I	J	K	L
1	sample ID						
2	investgated by						
3	date						
4	elevation						
5							
6	feature						
7	element						
8	detail						
9							
10	location						
11							
12	notes						
13							
14							
15							
16							
17	substrate						
18	finishes						
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							

Suspected finish campaigns are highlighted as follows: 1st campaign in red.
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.

Colonel Barrett Farm
Room 104 - Kitchen

	A	M	N	O	P
1	sample ID				
2	investgated by				
3	date				
4	elevation				
5					
6	feature				
7	element				
8	detail				
9					
10	location				
11					
12	notes				
13					
14					
15					
16					
17	substrate				
18	finishes				
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					

Suspected finish campaigns are highlighted as follows: 1st campaign in red.
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.