

Colonel Barrett Farm
Room 203 - East Chamber

	A	B	C	D	E	F	G	H	I	J	K
1	sample ID	CBF-203-A	CBF-203-B	CBF-203-C	CBF-203-D	CBF-203-E	CBF-203-F	CBF-203-G	CBF-203-H	CBF-203-I	CBF-203-J
2	investigated by	JBV	JBV	JBV	JBV	JBV	JBV	JBV	JBV	JBV	JBV
3	date	1/14/10	1/14/10	1/14/10	1/14/10	1/14/10	1/14/10	1/14/10	1/14/10	1/14/10	1/14/10
4	elevation	east	SE	north	west	west	west	west	west	west	north
5											
6	feature	baseboard	SE post casing	door casing	closet door	panel wall	panel wall	door to 202	chimney breast	mantle	beam (not cased)
7	element				lower panel			lower panel	vertical casing		
8	detail										
9											
10	location		above mopboard area			N of fireplace	N of closet				
11											
12											
13											
14	notes	few finishes relative to age of room				2 layers of panel wall					E elev beam same
15							same				
16											
17	substrate	wood		wood	wood	wood	wood				wood
18	finishes										wash?
19		red opaque (3 layers?)	red	red	red			red	red	red	red
20			glaze	glaze	glaze			glaze	glaze	glaze	... more
21		degraded glaze or brown yellowish?		more...	more...	clear coat or wash?	clear coat or wash?				
22		whites/off-whites (at least 5)				whites/off-whites	whites/off-whites				
23											
24											
25											
26											
27											
28											
29											
30											
31											
32											
33											

*Suspected finish campaigns are highlighted as follows: 1st campaign in red, 2nd campaign in blue, 3rd campaign in green
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.*

Colonel Barrett Farm
Room 203 - East Chamber

	A	L	M	N	O	P
1	sample ID	CBF-203-K	CBF-203-L	CBF-203-M		
2	investigated by	JBV	JBV	JBV		
3	date	1/14/10	2/21/20	1/21/10		
4	elevation	n/a (was south)	n/a	n/a		
5						
6	feature	window trim	floor	ceiling		
7	element					
8	detail					
9						
10	location	removed element	near W elev.			
11			@ nail hole			
12						
13						
14	notes	no red coatings				
15		c. 1905?				
16						
17	substrate	wood	wood	plaster		
18	finishes		soiled? or drk, degraded clear coat			
19			muddy green	multiple whites + off-whites		
20			red opaque			
21		clear coat	red opaque			
22		all whites	grayish green			
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						

*Suspected finish campaigns are highlighted as follows: 1st campaign in red, 2nd campaign in blue, 3rd campaign in green
The limitations of in-situ investigations can result in missed layers and incomplete stratigraphies.
Complete stratigraphies are not listed as the initial finish campaign(s) were the primary focus of the investigation.*